

CLASSIFIED MESSAGE

DATE 0315Z 25 JAN 61

SECRET

ROUTING	
1	4
2	5
3	6

TO DIRECTOR

FROM [REDACTED] 25X1A

ACTION: OPS (1-2-3-4)

INFO :S/C (5)

DL

TOR 0336Z 25 JAN 61

ROUTINE

IN 43858

TO

CITE [REDACTED] 0334

25X1A

25X1A

SLIPPER TANK FUEL PROBLEM ARTICLE 351. SUGGEST REMOVE RAM AIR TUBES, AUX TANK AND ENERGIZE A50126-1 SHUT OFF VALVE IF NOT ALREADY ACCOMPLISHED.

END OF MESSAGE

SECRET